

**Total Land Subsidence in the McMullen Valley, La Paz and Maricopa Counties
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data**

© MDA 2010 - 2015

Time Period of Analysis: 5.0 Years 05/01/2010 To 04/05/2015

Explanation


05/01/2010 To 04/05/2015

Total Land Subsidence

	Decorrelation/No Data
	Greater 40 cm (15.7 in)
	25 - 40 cm (9.8 - 15.7 in)
	15 - 25 cm (5.9 - 9.8 in)
	10 - 15 cm (3.9 - 5.9 in)
	6 - 10 cm (2.4 - 3.9 in)
	4 - 6 cm (1.6 - 2.4 in)
	2 - 4 cm (0.8 - 1.6 in)
	1 - 2 cm (0.4 - 0.8 in)
	0 - 1 cm (0 - 0.4 in)

- Subsidence Feature
- Earth Fissures
- Hardrock
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Railway

1:299,524



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey.
For information on earth fissures visit: www.azgs.az.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
Projection: Transverse Mercator
Datum: North American 1983
Units: Meter
Created: 4/8/2015

